

QA-448  
Crumpton Food Market  
Crumpton  
private

c. 1860's

The Crumpton Food Market is located on Broad Street opposite Second Street. It is a two story rectangular frame structure with gable facade and an extension to the rear. It is a plain building with handsome arched and pierced barge boards. Its store front is on one plane and has some of the same qualities as the Harrison Dry Goods Store, opposite. It is a good example of commercial structure dating from the third quarter of the 19th century.

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC

AND/OR COMMON

Crumpton Food Market

**2 LOCATION**

STREET &amp; NUMBER

Broad Street, opposite 2nd

CITY, TOWN

Crumpton

VICINITY OF

CONGRESSIONAL DISTRICT

First

STATE

Maryland

COUNTY

Queen Anne's

**3 CLASSIFICATION**

## CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

## OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED☒ not applicable

## STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO

## PRESENT USE

☐ AGRICULTURE☐ MUSEUM☒ COMMERCIAL☐ PARK☐ EDUCATIONAL☐ PRIVATE RESIDENCE☐ ENTERTAINMENT☐ RELIGIOUS☐ GOVERNMENT☐ SCIENTIFIC☐ INDUSTRIAL☐ TRANSPORTATION☐ MILITARY☐ OTHER:**4 OWNER OF PROPERTY**

NAME

Mr. &amp; Mrs. Howard M. Cole

Telephone #:

STREET &amp; NUMBER

Broad Street

CITY, TOWN

Crumpton

VICINITY OF

STATE, zip code

Maryland 21628

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE,

REGISTRY OF DEEDS, ETC. Queen Anne's County Courthouse

Liber #: CWC 17

Folio #: 119

STREET &amp; NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

QA-448

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Crumpton Food Market is located on the east side of Broad Street opposite Second. It is a large rectangular 2-story frame building with long one story extension on the back.

The gable facade has, on the first story, a deep shed-roof porch covering the store windows and central entrance. The facade is divided into five bays by plain chamfered pilasters supporting a bracketed cornice under the shed roof. In the four outer bays are large 4-pane windows with chamfered muntins (See Harrisons Dry Goods Store, opposite) and panels beneath. In the central bay is now a plain stock door, replacing the original double doors (now in storage) with 2-pane transom above.

On the second story are two windows with 6/6 sash and in the gable is a 4-pane semi-circular headed window. Along the overhanging barge board is an arched fascia with drop-like pendants and elliptical holes above each pendant. This motif also extends along the cornice and a smaller version along the porch.

On the south side are only two windows at the

CONTINUE ON SEPARATE SHEET IF NECESSARY

## CONTINUATION SHEET

## 7.1 DESCRIPTION

far ends of the structure on the first story. Only one exists on the north. On the back gable there are two windows on the second story. The barge board is devoid of decoration on the gable.

The low one-story wing out the back has two windows on the south and one on the north. In the center of the gable is a double freight door.

The body of the building is covered with asbestos siding.

Inside, the main part has only one room with a girder extending north-south. Two cast iron columns support the girder. Part of the original shelving is still in place between the two windows of the south wall. The window trim has an arched header. The ceiling is covered with beaded boards and there is a crown molding around the outside walls.

In the southeast corner is an enclosed stair to the second story. It now rises from the center of the building but originally rose from the south wall. In the center of the east wall is a double door, the leaves being unequal in width. They are made of two thicknesses of boards at right angles to another. The back storage area appears to have been added at two different times for the weather-board of the original section and of the first section are still exposed inside.

## CONTINUATION SHEET

## 7.2 DESCRIPTION

On the second story the building is divided into four rooms. The stair is in the southeast corner and has a well-made balustrade with tapered champhered newels and square balusters. A plaster wall extends north-south enclosing about one third of the total space. A beaded girder extends east-west and is supported on turned wood columns. A board partition parallels the girder to the north.

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
REHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Crumpton Food Market is located on Broad Street opposite Second Street. It is a two story rectangular frame structure with gable facade and an extension to the rear. It is a plain building with handsome arched and pierced barge boards. Its store front is on one plane and has some of the same qualities as the Harrison Dry Goods Store, opposite. It is a good example of commercial structure dating from the third quarter of the 19th century.

CONTINUE ON SEPARATE SHEET IF NECESSARY

# 9 MAJOR BIBLIOGRAPHICAL REFERENCES

QA-448

CONTINUE ON SEPARATE SHEET IF NECESSARY

## 10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

### 11 FORM PREPARED BY

NAME / TITLE

Michael O. Bourne, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

9/15/83

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.


The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

# CRUMPTON

QUEEN ANNE CO.

Dists. Nos. 1 & 2



Lake Griffing, Stevenson  
Atlas, 1877

1976 reprint

QA-448